

## Bobina de encendido SKCO-0070095

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN  
REFERENZE

 Image not found or type unknown

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN  
REFERENZE

 image not found or type unknown



## OEM Reference

FORD	0997001120
FORD	6R8312A366AA
JAGUAR	AJ810445
JAGUAR	AJ83415
JAGUAR	AJ87644
LAND ROVER	4526466
LAND ROVER	4744015

## OEM Cross Reference

ESEN SKV	03SKV176
METZGER	0880444
MEAT & DORIA	10648
INTERMOTOR	12442
HITACHI	133891
HITACHI	133891
HITACHI	133891
WE PARTS	220830389
OSSCA	22854
OSSCA	22854
VALEO	245388
VALEO	245388
NGK	48267
AIRTEX	5C1420
STELLOX	6100140SX
RIDEX	689C0092
HOFFER	8010648
FAE	80361
MAPCO	80921
IAP QUALITY PARTS	81614052
SIDAT	8530484
FISPA	8530484
ERA	880430
TRISCAN	886010020
CHAMPION	BAEA196E
CHAMPION	BAEA196E
ÜRO Parts	C2S42673
CSV electronic parts	CBE5436
MOBILETRON	CF78
LEMARK	CP151
FUELPARTS	CU1329
LUCAS ELECTRICAL	DMB1112
ELTA AUTOMOTIVE	EE5048
DELPHI	GN10448

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN  
REFERENZE

 Image not found or type unknown

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN  
REFERENZE

 Image not found or type unknown

**OEM**