

Bobina de encendido SKCO-0070269

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN
REFERENZE

 Image not found or type unknown

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN
REFERENZE

 Image not found or type unknown



OEM Reference

HITACHI	138814
HONDA	30500PM5A02
HONDA	30500PM5A03
ROVER	DLB705
ROVER	GCL161

OEM Cross Reference

BorgWarner (BERU)	0040100276
MEAT & DORIA	10431
BREMI	11886
INTERMOTOR	12618
INTERMOTOR	12618
HITACHI	138814
HITACHI	138814
HITACHI	138814
HUECO	138814
HUECO	138814
EFI AUTOMOTIVE	155086
NGK	48098
JAPKO	78402
HOFFER	8010431
SIDAT	8530100
FISPA	8530100
ERA	880052
FACET	96113
BLUE PRINT	ADH21477
CHAMPION	BAEA276
CHAMPION	BAEA276
JAPANPARTS	BO402
MOBILETRON	CH01
TESLA	CL500
WAI	CUF73
LUCAS	DLB705
DELPHI	GN10284
DELPHI	GN10284
NPS	H536A06
KAVO PARTS	ICC2029
JANMOR	JM5176
VEMO	V26700001
QUINTON HAZELL	XIC8116